




No. 15 - Clockwise (rightward, viewer's right) continuation of the view in Photograph No. 13. No damages were visible on the right (viewer's right) of the scratches.



No. 16 - Clockwise (rightward, viewer's right) continuation of the view in the above Photograph. Note evidence of physical damages were visible in this area.



No. 17 - Clockwise (rightward, viewer's right) continuation of the view in the immediate preceding Photograph. Note evidence of physical damages were visible in this area.



No. 18 - Clockwise (rightward, viewer's right) continuation of the view in the above Photograph. Note evidence of physical damages were visible in this area.