


No. 19 - Clockwise (rightward direction, viewer's right) continuation of the view in the immediate preceding Photograph. Note evidence of physical damages were visible in this area.



No. 20 - Clockwise (rightward, viewer's right) continuation of the view in the above Photograph. Note evidence of physical damages were visible in this area.



No. 21 - Clockwise (rightward direction, viewer's right) continuation of the view in the immediate preceding Photograph. Note evidence of physical damages were visible in this area.



No. 22 - Clockwise (rightward, viewer's right) continuation of the view in the above Photograph. Note evidence of physical damages were visible in this area.