




No. 23 - View of the bottom busbars. No evidence of physical damages were present.



No. 24 - Partial view of the inner wall of the Reactor. No evidence of physical damage was present.



No. 25 - The same as in the immediate preceding Photograph but from a different angle.



No. 26 - The same as in the above Photograph but a different area.